

ARDENT COOLING
PASSIONATE ABOUT COOLING

SERVICE RATE CARD · NOVEMBER 2026

Fixed, installed and serviced.

Clear prices for air conditioners, fridges and freezers, gas cookers and washing machines — for one-off jobs and corporate maintenance contracts across Abuja, Lagos, Port Harcourt and the North.

Air Conditioners	Refrigerators & Freezers	Gas Cookers	Washing Machines
From ₦12,000	From ₦20,000	From ₦30,000	From ₦30,000

+234 816 360 0004 · Call or WhatsApp
Switchboard +234 201 887 6457 ext. 104

team@ardentcooling.com · ardentcooling.com
Willdot Plaza, 903 Obafemi Awolowo Way, Utako, Abuja

Air Conditioners

From **₦12,000**

Split, standing, window, cassette, ducted and VRF — serviced, repaired, installed and relocated.

SERVICE	UNIT / SIZE	PRICE	BASIS
General servicing Filter & coil wash, drain flush, gas pressure check, electrical check, test run	Split 1HP–1.5HP	**₦25,000 – ₦30,000**	Labour
	Split 2HP–2.5HP	**₦25,000 – ₦30,000**	Labour
	Standing / floor 2HP–3HP	**₦30,000 – ₦40,000**	Labour
	Standing / floor 5HP	**₦35,000 – ₦45,000**	Labour
	Window unit	**₦20,000 – ₦25,000**	Labour
	Cassette unit	**₦25,000 – ₦40,000**	Labour
	Ducted unit (per indoor unit)	**₦40,000 – ₦60,000**	Labour
	VRF / central (per indoor unit)	**₦50,000 – ₦60,000**	Labour
Gas top-up (R22 / R410A / R32) Leak check and top-up to correct pressure	Split 1HP–1.5HP	**₦25,000 – ₦75,000**	Incl. parts
	Split 2HP–2.5HP	**₦25,000 – ₦90,000**	Incl. parts
	Standing / floor 2HP–3HP	**₦40,000 – ₦120,000**	Incl. parts
	Standing / floor 5HP	**₦60,000 – ₦150,000**	Incl. parts
	Window unit	**₦25,000 – ₦40,000**	Incl. parts
Full gas recharge after leak repair Vacuum, recharge, pressure test	Per unit	**₦25,000 – ₦90,000**	Incl. parts
Leak detection & repair (brazing) Locate leak, braze/flare repair, pressure test	Per leak point	**₦25,000 – ₦70,000**	Labour
Installation of new unit Mounting, standard installation kit (up to 3m piping), vacuum, commissioning	Split 1HP–1.5HP	**₦30,000 – ₦40,000**	Labour
	Split 2HP–2.5HP	**₦30,000 – ₦40,000**	Labour
	Standing / floor 2HP–3HP	**₦40,000 – ₦50,000**	Labour
	Standing / floor 5HP	**₦40,000 – ₦60,000**	Labour
	Window unit	**₦20,000 – ₦25,000**	Labour
	Cassette unit	**₦30,000 – ₦50,000**	Labour
	Ducted unit	**₦80,000 – ₦150,000**	Labour
	VRF / central system	*Quote on inspection*	On inspection
Extra copper piping & insulation Above the standard 3m	Per metre	*Quote on inspection*	Incl. parts
Extra trunking / cable Neat finishing beyond standard length	Per metre	*Quote on inspection*	Incl. parts

SERVICE	UNIT / SIZE	PRICE	BASIS
Wall bracket supply & fitting Outdoor unit bracket	Per set	*Quote on inspection*	Incl. parts
Uninstallation Gas pump-down, removal, capping of pipes	Split unit	**₦30,000 – ₦50,000**	Labour
Relocation (uninstall + reinstall) Pump-down, move within same site, reinstall, commission	Split unit	**₦40,000 – ₦100,000**	Labour
Uninstallation Gas pump-down, removal, capping of pipes	Standing / floor unit	**₦35,000 – ₦90,000**	Labour
Relocation (uninstall + reinstall) Pump-down, move within same site, reinstall, commission	Standing / floor unit	**₦45,000 – ₦90,000**	Labour
Capacitor replacement Fault diagnosis and replacement	Per unit	**₦12,000**	Incl. parts
Fan motor replacement (indoor or outdoor) Removal and fitting of new motor	Per motor	**₦36,000**	Labour
PCB / control board repair Component-level repair	Per board	**₦55,000 – ₦90,000**	Incl. parts
PCB / control board replacement Fitting of new board (board priced separately)	Per board	**₦60,000 – ₦120,000**	Labour
Compressor replacement Removal, fitting, brazing, vacuum, gas charge, test	Split 1HP–1.5HP	*Quote on inspection*	Labour
	Split 2HP–2.5HP	*Quote on inspection*	Labour
	Standing / floor 2HP–5HP	*Quote on inspection*	Labour
Water leaking / drain blockage fix Drain line clearing, tray cleaning, re-levelling	Per unit	**₦15,000 – ₦25,000**	Labour
Thermostat / sensor / contactor replacement Diagnosis and replacement	Per item	**₦30,000 – ₦50,000**	Incl. parts
Supply of new AC units Supply of genuine units (brand & size on request)	Per unit	*Quote on inspection*	On inspection

Refrigerators & Freezers

From **₦20,000**

Domestic and commercial: single and double-door fridges, chest and upright freezers, display chillers.

SERVICE	UNIT / SIZE	PRICE	BASIS
General servicing & condenser clean Condenser/coil clean, door seal check, temperature check	Per unit	**₦25,000 – ₦40,000**	Labour
Gas refill Leak check, vacuum and refill	Single-door fridge	**₦20,000 – ₦50,000**	Incl. parts
	Double-door fridge	**₦20,000 – ₦50,000**	Incl. parts
	Side-by-side / American fridge	**₦20,000 – ₦50,000**	Incl. parts
	Chest freezer (small, up to 200L)	**₦20,000 – ₦50,000**	Incl. parts

SERVICE	UNIT / SIZE	PRICE	BASIS
	Chest freezer (large, over 200L)	₦20,000 – ₦50,000	Incl. parts
	Upright freezer	₦20,000 – ₦50,000	Incl. parts
	Display chiller / showcase	₦20,000 – ₦50,000	Incl. parts
Leak detection & repair Locate and repair gas leak	Per leak point	₦20,000 – ₦50,000	Labour
Thermostat replacement Diagnosis and replacement	Per unit	₦20,000 – ₦50,000	Incl. parts
Relay / overload protector replacement Starting fault repair	Per unit	₦20,000 – ₦50,000	Incl. parts
Compressor replacement Fitting, brazing, vacuum, gas charge, test	Domestic fridge / freezer	*Quote on inspection*	Labour
	Commercial / display unit	*Quote on inspection*	Labour
Fan motor replacement Evaporator or condenser fan	Per motor	₦30,000 – ₦50,000	Incl. parts
Defrost timer / heater replacement (frost-free) Fixes icing and poor cooling	Per unit	₦30,000 – ₦50,000	Incl. parts
Door gasket / seal replacement Supply and fit	Per door	₦30,000 – ₦50,000	Incl. parts
PCB / inverter board repair Component-level repair	Per board	₦30,000 – ₦50,000	Incl. parts
Commercial chiller / cold display servicing Full service for shops, restaurants and supermarkets	Per unit	₦30,000 – ₦50,000	Labour

Gas Cookers

From **₦30,000**

Table-top, standing and built-in cookers — serviced, repaired, safety-checked and connected.

SERVICE	UNIT / SIZE	PRICE	BASIS
Full servicing Burner & jet cleaning, flame adjustment, ignition check, gas leak test	Table-top (2–3 burner)	₦30,000 – ₦50,000	Labour
	Standing cooker, 4 burner with oven	₦30,000 – ₦50,000	Labour
	Standing cooker, 5–6 burner / large oven	₦30,000 – ₦50,000	Labour
	Built-in hob	₦30,000 – ₦50,000	Labour
Ignition / spark system repair Igniter, spark module or switch	Per cooker	₦30,000 – ₦50,000	Incl. parts
Knob / gas valve replacement Replace faulty valve or knob	Per valve	₦30,000 – ₦50,000	Incl. parts
Oven thermostat / burner repair Oven not heating or uneven heat	Per oven	₦30,000 – ₦50,000	Incl. parts
Glass top / lid replacement Supply and fit	Per cooker	*Quote on inspection*	Incl. parts

SERVICE	UNIT / SIZE	PRICE	BASIS
Gas leak test & safety check Full leak test of cooker, hose and regulator	Per cooker	**₦30,000 – ₦50,000**	Labour
Hose & regulator replacement Supply and fit approved hose/regulator	Per set	**₦30,000 – ₦50,000**	Incl. parts
Installation & connection to gas cylinder Positioning, connection, leak test, demo	Per cooker	**₦30,000 – ₦50,000**	Labour
Connection to piped gas / gas line Connection and pressure test	Per cooker	*Quote on inspection*	On inspection
Uninstallation / relocation Safe disconnection and reconnection	Per cooker	**₦30,000 – ₦50,000**	Labour

Washing Machines

From **₦30,000**


Top-load, front-load and twin-tub machines — repaired, serviced and plumbed in.

SERVICE	UNIT / SIZE	PRICE	BASIS
General servicing Drum, filter, hoses and seals check, descale, test cycle	Top-load	**₦30,000 – ₦50,000**	Labour
	Front-load	**₦30,000 – ₦50,000**	Labour
	Twin-tub	**₦30,000 – ₦50,000**	Labour
Drain pump replacement Not draining / error codes	Per machine	**₦30,000 – ₦50,000**	Incl. parts
Water inlet valve replacement Not filling or overfilling	Per machine	**₦30,000 – ₦50,000**	Incl. parts
Door lock / interlock replacement Door won't lock or open	Per machine	**₦30,000 – ₦50,000**	Incl. parts
Drum bearing & seal replacement Noisy spin, leaks from drum	Top-load	*Quote on inspection*	Incl. parts
	Front-load	*Quote on inspection*	Incl. parts
Drive belt replacement Drum not turning	Per machine	**₦30,000 – ₦50,000**	Incl. parts
Motor / carbon brush repair Motor not running	Per machine	**₦30,000 – ₦50,000**	Incl. parts
PCB / control board repair Component-level repair	Per board	**₦30,000 – ₦50,000**	Incl. parts
Heater element replacement Not heating water	Per machine	**₦30,000 – ₦50,000**	Incl. parts
Shock absorber / suspension replacement Violent shaking during spin	Per set	**₦30,000 – ₦50,000**	Incl. parts
Leak repair (hoses, seals) Locate and fix leaks	Per machine	**₦30,000 – ₦50,000**	Incl. parts
Installation & plumbing Unpack, remove transit bolts, connect inlet & drain, level, test cycle	Per machine	**₦30,000 – ₦50,000**	Labour
Uninstallation / relocation Disconnect, refit transit bolts, reconnect	Per machine	**₦30,000 – ₦50,000**	Labour

Corporate Servicing

Per unit, per visit

Scheduled preventive maintenance for offices, factories, banks, schools, hotels and estates — with asset tagging, a full service history for every unit and one invoice.



EQUIPMENT	MONTHLY VISITS	QUARTERLY VISITS
AC preventive maintenance — split unit	₦22,000	₦25,000
AC preventive maintenance — standing / floor unit	₦28,000	₦30,000
AC preventive maintenance — cassette / ducted unit	₦30,000	₦32,000
AC preventive maintenance — VRF indoor unit	₦40,000	₦45,000
Refrigerator / freezer maintenance	₦22,000	₦25,000
Commercial chiller / display maintenance	₦25,000	₦30,000
Gas cooker / kitchen equipment safety service	₦25,000	₦30,000
Washing machine maintenance	₦25,000	₦30,000

4 units
Minimum for a maintenance contract

₦15,000
Priority call-out between scheduled visits

Monthly
Billing — one invoice for all sites

How our pricing works

- All prices are in Nigerian Naira and exclude VAT. Where a range is shown, the final price depends on the unit, its condition and access, and is confirmed in a written quote before work starts.
- **Labour** — price covers workmanship; any parts needed are quoted separately. **Incl. parts** — price includes the standard parts or gas for that job.
- **Quote on inspection** — jobs such as compressor replacement, VRF installation and new unit supply are priced after a technician has assessed the site.
- We confirm the call-out fee when you book. Prices are the same for every customer — home or business.
- Rates valid from November 2026 and may change without notice. Ardent Cooling Limited · RC 1677595 · A Lu Gold company.

Book a technician

ardentcooling.com/book · Mon–Fri 9:00–17:00 · Sat 10:00–14:00

+234 816 360 0004
team@ardentcooling.com